MEASURE NUMBER: SB 465STATUS: A-EngrossedSUBJECT: Directs the Legislative Administration Committee to repair and restore the stairwells on
either side of the rotunda of the State CapitolGOVERNMENT UNIT AFFECTED: Legislative Administration CommitteePREPARED BY: Kim ToREVIEWED BY: Daron HillDATE: May 12, 2009

EXPENDITURES:

See Analysis

<u>2009-2011</u> <u>2011-2013</u>

EFFECTIVE DATE: On Passage

LOCAL GOVERNMENT MANDATE: This bill does not affect local governments' service levels or shared revenues sufficient to trigger Section 15, Article XI of the Oregon Constitution.

ANALYSIS: This measure directs the Legislative Administration Committee to use volunteers and moneys available from the Capitol Renovation Project to: (1) repair and restore the stairwells on either side of the rotunda of the State Capitol and equip the stairwells with modern glass skylights over the stairs; and (2) clean and polish all brass pieces in the original part of the State Capitol, not including the window frames. The bill requires the project to be completed by no later than November 1, 2009. In addition to moneys available from the Capitol Renovation Project, the bill authorizes the Legislative Administration Committee to accept grants, donations, contributions or gifts from any source to fund the repair and restoration.

The Legislative Administration Committee reports that the contractor estimate for repair and restoration of the stairwells as stipulated by this measure is \$89,345. The cost to clean and polish the brass pieces is approximately \$925 including the rental of scaffolding and polishing supplies. This \$925 amount does not include cleaning and polishing of window frames. The Legislative Administration Committee estimates that an equivalent of 292 volunteer hours would be needed to polish all the brass pieces in the original part of the State Capitol, not including window frames.

This bill requires budgetary action for Other Funds expenditure limitation.